NEW SITE IDENTIFICATION

Рa	rt A - To Be Completed By Observer					
1.	Person Initiating Report: Jacob Harris	Phone: 526-1877				
	Contractor WAG Manager: Douglas Burns	Phone: 526-4324				
2.	Site Title: 042, Construction Debris Northeast of EOCR					
3.	Describe the conditions that indicate a possible inactive or unreported waste site. Include location and description of suspicious condition, amount or extent of condition and date observed. A location map and/or diagram identifying the site against controlled survey points or global positioning system descriptors shall be included to help with the site visit. Include any known common names or location descriptors for the waste site.					
	The area north of EOCR/STF has several areas of construction debris. During the August 1999 visit observed construction debris included a pile of broken sewer pipe, a pile of broken cinder block, a rusty 55 gallon drum, pieces of reinforced concrete, stovepip cable, re-bar, etc. Also, northwest of EOCR is an area where it appears dirt has been pushed over a trash pile. Some items in the pile are wood, metal, rubber, hose, cable, wire, etc. The GPS coordinates of the pile of broken sewer pipe are N677753.18 by E306432.48. The GPS coordinates of the trash pile partially covered with dirt are N677764.29 by E305383.90. The reference number for this site is 042 and can be found on the summary map as provided.					
Pai	rt B – To Be Completed By Contractor WAG Manager					
4.	Recommendation:					
	This site meets the requirements for an inactive waste site, requires investigation, and should be included in the INEEL FFA/CO Action Plan. Proposed Operable Unit assignment is recommended to be included in the FFA/CO. WAG: 10 Operable Unit: 10-08					
	This site DOES NOT meet the requirements for an inactive waste site, DOES NOT require investigation and SHOULD NOT included in the INEEL FFA/CO Action Plan.					
5.	Basis for the recommendation:					
	The conditions that exist at this site indicate the potential for an inactive waste site according to Section 2 of MCP-3448 Reporting or Disturbance of Suspected Inactive Waste Sites.					
	•					
	The basis for recommendation must include: (1) source description; (2) concern; and (4) descriptions of interfaces with other programs, as applications.	exposure pathways; (3) potential contaminants of able (e.g., D&D, Facility Operations, etc.)				
6.	Contractor WAG Manager Certification: I have examined the proposed sibelieve the information to be true, accurate, and complete. My recommer	te and the information submitted in this document a				

Signature:_

Date: 5/25/00

NEW SITE IDENTIFICATION

Part C - To Be Comp	eted By INEEL FFAC	O/CO WAG	Managers		
7. WAG Operable Unit:	:				
DOE WAG Manager	Concurrence:	☑ Concur	with recommendation		Do not concur with the recommendation
Signature: Pat	ti Kroupe				
Date:	131/00	_			
EAP WAG Managers	s Concurrence:	Concur	with recommendation.		Do not concur with the recommendation
Signature:	- Bush				
Date:(0(5/00				
State of Idaho WAG	Managers Concurrence:	Concur	with recommendation.		Do not concur with the recommendatio
Signature:	eno Winter	1			
Date:	-14-00	_			
Explanation follows:					
Part D – To Be Compl	eted By The INEEL F	FA/CO Resp	onsible Program M	lanage	ers (RPM's)
8. FFA/CO RPM's Cond	currence:				
For DOE-ID			-		
Name: Kathleen Hain	Signature: Zath	leer E Hair	Date: 7 //2/00	- A	Concur Do not concur. Explanation follows:
For EPA Region X	1./.	1			
Name: Wayne Pierre	Signature:	Vicea	Date: 7 15 102	- }	Concur Evalenation follows:
For State of Idaho		. / /			Do not concur. Explanation follows:
Name: Dean Nygard	Signature:	A pegas	Date: 4 128/00	_ 区	Concur
	0			Ц	Do not concur. Explanation follows:



MISC-42, Construction Debria Northeast of EOCR



MISC-42, Construction Debris Northeast of EOCR